

TITLE : Update payment devices Bolero
MODEL : Bolero 11 / 21, Bolero 32 / 33 / 43
DATE : 2024-09-06 **NUMBER** : SI240906-A

Reason for sending you this information

A payment device update for Bolero machines has just been released.

Part and software information:

This is a 2-part upgrade:

1. Bolero firmware 2.2.2 update
 - » This firmware can be updated on the machine using a USB-based device.
2. MDB board update, version H
 - » In order to work correctly with the Firmware 2.2.2, the MBD board must be at least version H. The version of the MDB card can be found on the label on the back of the MDB card, 271.037.000/H. Version H of the MDB board was introduced in February 2024.
(Unfortunately, the Bolero's MDB board cannot be updated with software.)

► *Lower versions of the Bolero firmware and/or the MDB board may cause problems with payment devices.*

The first machine with the new Firmware 2.2.2 has serial number **020002520541**

Changed Spare Part:

- Bolero firmware-2.2.2
 - MDB board version H
- If the Bolero is already equipped with an MDB set, it is also possible to order the MDB board 6.271.037.000 separately.

New Spare Part:

- None

Deleted Spare Part:

- None